

Problem Report

Report Number: 2

Project Name: TeraPixel APS for CALICE **v1.1**

Item: Charge injection from MSO power supply to preamplifier

Problem
<p>Injection from the MSO power supply is observed in the test pixel preamplifier.</p> <p>Bulk pixels are reset and a small signal is seen in the test pixel – this might lead to runaway/avalanche/crosstalk if sufficient bulk pixel fire to cause more local hits or unexpected behaviour during a reset of all bulk pixels.</p> <p>The likely cause is attributed to the fact that the logic buffers that generate the RST and RSTB signals (per pixel) are supplied with VDD1V8MSO – hence any significant disturbance on this power net can be seen on RST (or RSTB, whichever is held high) and therefore can couple into the preamplifier.</p> <p>A similar (but small) effect is seen in simulation if series resistance is added to the MSO power net, although this doesn't fully account for the injection seen under test.</p> <p>Originator (Sign/Date)</p> <p>JC</p> <p>Project Manager (Sign/Date)</p>
Remedial Action
<p>No remedial action is possible post manufacture</p> <p>It remains to be seen whether this effect causes noticeable effects in the bulk performance – the most likely occurrence of this phenomena is when all the bulk pixels are reset, hence everything that could be coupled to is also in reset – although some odd effects might be seen while coming out of reset, this is before a bunch train and should not impact normal operation.</p> <p>If pixel monostables are biased with a very high current, or a great many fire at once, coupling of this nature may also be observed.</p> <p>For any future design the power supply for these buffers should be considered carefully, to ensure it is clean.</p> <p>Project Manager (Sign/Date)</p> <p>JC</p>