

chip = 2 : enable = 0 : gain = 0 & gain = 1

| hist    |        |
|---------|--------|
| Entries | 200    |
| Mean x  | 2733   |
| Mean y  | -132.5 |
| RMS x   | 4507   |
| RMS y   | 73.56  |

